



408009



AN
INSPECTION REPORT
OF
WEATHER AND RAD-SAFE STATIONS

BEST COPY AVAILABLE

REPOSITORY Nevada Operations Office
COLLECTION 71 A 856
BOX No. 71249 or 151
FOLDER None

30 July Thru 3 August 1959



14051

[REDACTED]

At 1300 the party departed Ujelang and arrived at Ponape at 1500. Settled in quarters, made arrangements for meals and proceeded to Distad Headquarters to confer with Mr. Finale, the acting Distad. In company of Messrs. Sullivan and Hirada, the party made an inspection of the weather station and determined the following to be the present condition of the station.

WEATHER STATION - PONAPE

1. The weather station building, which is being operated by the U.S. Weather Bureau, appears to be in very good condition structurally. A small amount of dry rot occurs at the base of the stair posts and Mr. Hirada intends to have the posts incased in concrete approximately 12" above the footings. During windy rainstorms, a small portion of the roof develops slight leaks. This he proposes to repair with mastic and metal flashing. Mr. Hirata further proposes to build a small shelter to house an emergency generator. This will keep the station operable during power failures at the main plant.

Returned to quarters 1830 30 JULY 1959.

*See addendum #2 for applicable photos.

31 JULY 1959

At 0600 party and plane crew arrived at Sea-plane ramp, in a rain that increased to a very heavy downpour by 0700. The plane commander announced an indefinite delay in take-off. At 1000 the flight was definitely postponed until the following day. At 1100 returned to quarters. Rain all day and part of the night.

1 AUGUST 1959

At 0610, party departed Ponape and arrived at Kapingamarangi at 1010. The party went ashore on Fumatahachi Island and inspected the weather station. Following was determined to be the present condition of the station.

WEATHER STATION - KAPINGAMARANGI

1. PUMP HOUSE - Slight weather damage to roof, one section of aluminum sheathing missing and one aluminum window shutter is hanging by one hinge. Otherwise in good condition.
2. SUPPLY & OPERATIONS BLDG. - Apparently in very good condition externally. Building was locked but one shutter was not secured. No evidence of entry.
3. WATER TOWER - Fairly good condition. Reusable for at least one year from this date.
4. POWER & DISTALLATION - In good condition.
5. MESS HALL - Bldg. locked - exterior in very good condition.
6. REEFER SHED - Bldg. in good condition all hardware shows signs of corrosion. The electrical outlets, breakers and switch gear are quite heavily corroded and will probably have to be replaced.
7. BARRACKS #1 - Bldg. locked - exterior in good condition.
8. DAY ROOM - Bldg. locked - exterior in good condition.
9. BARRACKS #2 - Bldg. locked - exterior in good condition.
10. RAWINSODE PAD - In good condition.
11. ANTENNA POLES - In good condition.
12. HOMER SHELTER - This was removed and returned to EPG during the Hardtack Roll-Up.
13. PIPING SYSTEM, OUT DOOR-SEWER - The 8" Spiral Weld steel pipe outfall is disconnected from the first length. Seven lengths, still joined together lie near by on the reef and are recoverable and reusable.

[REDACTED]

GENERAL - Roofs of some of the buildings are slightly dented, probably from falling coconuts. Nine drums of fuel oil are stored alongside the Power and Distillation building. Only slightly rusty.

The appearance of this station is very good and there are no indications that it has been disturbed by the natives. It could quickly and easily be reactivated.

All screening wherever indicated on the plans, should be replaced.

At 1415, the party departed Kapingamarangi and arrived at Ponape 1630. 1 AUGUST 1959.

* See addendum #3 for applicable photos.

2 AUGUST 1959

At 0704, the party departed Ponape and arrived at Kusaie at 1030. The party went ashore and inspected the weather station. Following was determined to be the present condition of the station.

WEATHER STATION - KUSAIE

SITE "A"

1. SUPPLY & OPERATIONS - In good condition.
2. GENERATOR SHED - In good condition.
3. RAWINSONDE TOWER - In good condition. However the vertical steel poles and steel angles are beginning to show signs of rust.
4. PIT LATRINE - Apparently good condition, but should be replaced.
5. FUEL TANK BASE - In good condition.
6. REEFER SHED - In good condition.

SITE "B"

1. REEFER SHED - In good condition.
2. MESS HALL - Two of the doors are beyond repair due to dry rot and need to be replaced. A screen is missing from one window. Otherwise the building is in good condition.
3. DAY ROOM - Is in good condition.
4. BARRACKS - Is in good condition.
5. BARRACKS - Is in good condition.
6. POWER HOUSE - Is in good condition.
7. DISTILLATION SHED - Is in good condition.
8. WATER TOWER - There is evidence of dry rot in the bottom 6 inches of each of the tower legs. Also, several planking are missing from the platform. Repairs could be easily made to place the tower in good working condition.
9. BARRACKS - In good condition, except for one door which is beyond repair with dry rot and needs to be replaced.
10. ANTENNA POLES - In good condition.
11. SEWER OUTFALL - Has disappeared and needs to be replaced.

~~SECRET~~

GENERAL - The appearance of the station indicates that it has not been disturbed by the natives, and could be quickly and easily reactivated. All screening should be replaced where ever called for on the plans.

At 1240, the party departed Kusaie and arrived at Kwajalein at 1615 hours 2 August 1959. Arrangements were made for quarters and conferred with the Duty Officer of the Air Depot to schedule our flight to Utirik and Wotho the following day.

* See addendum #1 for applicable photos.

~~SECRET~~

3 AUGUST 1959

At 0850 hours the party departed Kwajalein and arrived at Utirik at 1030 hours. The party went ashore and inspected the weather station. Following was determined to be the present condition of the station.

WEATHER STATION - UTIRIK

1. BARRACKS #1 - In good condition.
2. BARRACKS #2 - In good condition except for one shutter hinge missing.
3. DAY ROOM - In good condition.
4. PUMP SHED - In good condition.
5. OPERATIONS & SUPPLY - In good condition.
6. RAWINSONDE PAD - In good condition.
7. REEFER BANKS - In good condition.
8. MESS HALL - In good condition.
9. WATER TOWER - In good condition.
10. POWER & DISTILLATION - In good condition.
11. ANTENNA POLES - In good condition.
12. PIER - In fair, useable condition.

GENERAL

The appearance of the station indicates that it has not been disturbed by the natives. All closed buildings are secured with locks. This station could easily be activated. All screening, where called for on the plans needs to be replaced. There is a superabundance of flies.

* See addendum #5 for applicable photos.

~~CONFIDENTIAL - SECURITY INFORMATION~~

At 1150 hours the party departed Utirik and arrived at Wotho at 1330 hours. The party went ashore and inspected the weather station. The following was determined to be the present condition of the station.

RAD-SAFE STATION - WOTHO

1. DAY ROOM - Frame in good condition. Needs new tent and fly.
2. TENT #1 - DITTO
3. TENT #2 - DITTO
4. TENT #3 - DITTO
5. MESS HALL - Frame in good condition. Needs new tent and fly and screened.
6. REEFER TENT - DITTO
7. RAD-SAFE TENT - Frame in good condition. Needs new tent and fly.
8. POWER & DISTILLATION - In good condition.
9. PIT LATRINE - Fair condition but should be replaced.
10. FIELD SHOWER - Frame in good condition. Needs canvas siding.
11. PUMP HOUSE - In good condition.
12. WATER TOWER - In good condition.

At 1500 hours the party departed Wotho and arrived at Eniwetok at 1630 hours. At 1700 hours departed Fred via H-21 Aircraft and arrived at Site Elmer at 1710 hours 3 August 1959.

* See addendum #6 for applicable photos.

EHW:JSC:dp

cc:

S. P. Howell, H/O, w/1 photo. encl.
C. J. Yokota, H/O, w/1 photo. encl.
USAEC, EBO, w/3 photo. encl.
H/O Chrono
H/O Central
J/S Chrono
J/S Central
J/S Estimating Dept.
J/S Engineering
J/S Engr. Reading File

~~CONFIDENTIAL - SECURITY INFORMATION~~




A D D E N D U M - - N O . 1

RAD-SAFE STATION * * UJELANG

PHOTOS

30 JULY 1959





CLASSIFICATION	CUO	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	COE	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS _____ %
<u>13-35-12-1</u>	<u>7-30-59</u>	<u>Ujelang</u>
NEGATIVE NO.	DATE	SITE
Pump House.		



CLASSIFICATION	CUO	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	COE	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS _____ %
<u>13-35-12-2</u>	<u>7-30-59</u>	<u>Ujelang</u>
NEGATIVE NO.	DATE	SITE



CLASSIFICATION	030	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	GCE	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS _____ %
<u>13-35-12-3</u>	<u>7-30-59</u>	<u>Ujelang</u>
NEGATIVE NO.	DATE	SITE
Shower		




CLASSIFICATION	030	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	GCE	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS _____ %
<u>13-35-12-4</u>	<u>7-30-59</u>	<u>Ujelang</u>
NEGATIVE NO.	DATE	SITE
WATER AND LAUNDRY BLDG		




CLASSIFICATION	CUO	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	COE	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS _____ %
<u>13-35-12-5</u>	<u>7-30-59</u>	<u>Ujalang</u>
NEGATIVE NO.	DATE	SITE
LIVING QUARTERS TENT		




CLASSIFICATION	CUO	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	COE	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS _____ %
<u>13-35-12-6</u>	<u>7-30-59</u>	<u>Ujalang</u>
NEGATIVE NO.	DATE	SITE
Living Quarters Tent		



CLASSIFICATION	030	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	COB	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS _____ %
<u>13-35-12-7</u>	<u>7-30-59</u>	<u>Ujelang</u>
NEGATIVE NO.	DATE	SITE
DATROOM		



CLASSIFICATION	030	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	COB	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS _____ %
<u>13-35-12-8</u>	<u>7-30-59</u>	<u>Ujelang</u>
NEGATIVE NO.	DATE	SITE



CLASSIFICATION	030	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	COE	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS _____ %
<u>13-35-12-9</u>	<u>7-30-59</u>	<u>Ujelang</u>
NEGATIVE NO.	DATE	SITE
POWER & DISTILLATION		



CLASSIFICATION	030	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	COE	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS _____ %
<u>13-35-12-10</u>	<u>7-30-59</u>	<u>Ujelang</u>
NEGATIVE NO.	DATE	SITE




A D D E N D U M * * N O . 2

WEATHER STATION - - P O N A P E

P H O T O S


30 JULY 1959



CLASSIFICATION	000	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	COE	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS _____ %
<u>13-35-12-12</u>	<u>7-30-99</u>	<u>Ponape</u>
NEGATIVE NO.	DATE	SITE
WEATHER STATION		



CLASSIFICATION	000	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	COE	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS _____ %
<u>13-35-12-13</u>	<u>7-30-99</u>	<u>Ponape</u>
NEGATIVE NO.	DATE	SITE
VIEW OF END OF STATION		




ADDENDUM ** NO. 3

WEATHER STATION -- KAPINGAMARANGI


PHOTOS

1 AUGUST 1959





CLASSIFICATION	CUO	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	COE	<input type="checkbox"/> PICTORIAL
13-35-12-14	8-1-59	<input type="checkbox"/> PROGRESS _____ %
NEGATIVE NO.	DATE	SITE
Kapingamarangi		
VIEW OF THE OPEN SIDE OF PREFHOUSE		



CLASSIFICATION	CUO	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	COE	<input type="checkbox"/> PICTORIAL
13-35-12-15	8-1-59	<input type="checkbox"/> PROGRESS _____ %
NEGATIVE NO.	DATE	SITE
Kapingamarangi		
VIEW OF ROOF SECTION POSING FROM THE CORNER ROOF		



CLASSIFICATION **000** INFORMATION
 PHOTOGRAPHER **COE** PICTORIAL
 PROGRESS _____ %
13-35-12-16 **8-1-59** **Kapingarangi**
 NEGATIVE NO. DATE SITE
VIEW OF SE END OF DAYROOM



CLASSIFICATION **000** INFORMATION
 PHOTOGRAPHER **COE** PICTORIAL
 PROGRESS _____ %
13-35-12-17 **8-1-59** **Kapingarangi**
 NEGATIVE NO. DATE SITE
VIEW OF E. SIDE OF DAYROOM



A D D E N D U M * * N O . 4

WEATHER STATION - - KUSAIB

PHOTOS


2 AUGUST 1959



CLASSIFICATION	000	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	COE	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS _____ %
<u>13-35-13-1</u>	<u>8-2-59</u>	<u>Kusafu</u>
NEGATIVE NO.	DATE	SITE
	KEEPER BLDG.	SITE "A"



CLASSIFICATION	000	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	COE	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS _____ %
<u>13-35-13-2</u>	<u>8-2-59</u>	<u>Kusafu</u>
NEGATIVE NO.	DATE	SITE



CLASSIFICATION	000	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	COE	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS _____ %
<u>13-35-13-3</u>	<u>8-2-59</u>	<u>KUSAIB</u>
NEGATIVE NO.	DATE	SITE
RANIRSONDE TOWER		SITE "A"




CLASSIFICATION	000	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	COE	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS _____ %
<u>13-35-13-5</u>	<u>8-2-59</u>	<u>KUSAIB</u>
NEGATIVE NO.	DATE	SITE
VIEW OF ROBERTS BLDG		SITE "A"



CLASSIFICATION	OUO	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	COB	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS _____ %
<u>13-35-13-6</u>	<u>8-2-59</u>	<u>Rusaie</u>
NEGATIVE NO.	DATE	SITE
PIT LATRINE		SITE "A"




CLASSIFICATION	OUO	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	COB	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS _____ %
<u>13-35-13-7</u>	<u>8-2-59</u>	<u>Rusaie</u>
NEGATIVE NO.	DATE	SITE
FUEL TANK & BASE		SITE "A"



CLASSIFICATION	000	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	COE	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS _____ %
<u>13-35-13-11</u>	<u>8-2-59</u>	<u>Kusale</u>
NEGATIVE NO.	DATE	SITE
VIEW SHOWING BOT ON DOOR BLDG. 10 SITE "B"		



CLASSIFICATION	000	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	COE	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS _____ %
<u>13-35-13-12</u>	<u>8-2-59</u>	<u>Kusale</u>
NEGATIVE NO.	DATE	SITE



CLASSIFICATION	000	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	COE	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS..... %
<u>13-35-13-13</u>	<u>8-2-59</u>	<u>Kusale</u>
NEGATIVE NO.	DATE	SITE
SW END BARRACKS BLDG. # 5		SITE "B"




CLASSIFICATION	000	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	COE	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS..... %
<u>13-35-13-14</u>	<u>8-2-59</u>	<u>Kusale</u>
NEGATIVE NO.	DATE	SITE
GREEN BANK & WATKINS FOLD		SITE "B"




CLASSIFICATION	000	<input checked="" type="checkbox"/>	INFORMATION
PHOTOGRAPHER	CCS	<input type="checkbox"/>	PICTORIAL
		<input type="checkbox"/>	PROGRESS _____ %
<u>13-35-13-15</u>	<u>8-2-59</u>	<u>Russia</u>	
NEGATIVE NO.	DATE	SITE	
VIEW OF DOOR SW END MESSHALL SITE "B"			




CLASSIFICATION	000	<input checked="" type="checkbox"/>	INFORMATION
PHOTOGRAPHER	CCS	<input type="checkbox"/>	PICTORIAL
		<input type="checkbox"/>	PROGRESS _____ %
<u>13-35-13-16</u>	<u>8-2-59</u>	<u>Russia</u>	
NEGATIVE NO.	DATE	SITE	
VIEW OF DOOR SW SIDE MESSHALL SITE "B"			



CLASSIFICATION	CUO	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	COE	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS _____ %
<u>13-35-13-17</u>	<u>8-2-59</u>	<u>Kumalo</u>
NEGATIVE NO.	DATE	SITE
WATER TOWER		SITE "B"



CLASSIFICATION	CUO	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	COE	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS _____ %
<u>13-35-13-18</u>	<u>8-2-59</u>	<u>Kumalo</u>
NEGATIVE NO.	DATE	SITE
SECTION OF WATER TOWER BASES SITE "B"		



A D D E N D U M * * N O . 5

WEATHER STATION - - UTIRIK

PHOTOS

3 AUGUST 1959





CLASSIFICATION	CUO	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	COE	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS _____ %
<u>13-35-14-1</u>	<u>8-3-59</u>	<u>Utirik</u>
NEGATIVE NO.	DATE	SITE
BARRACKS BLDG. / 1		



CLASSIFICATION	CUO	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	COE	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS _____ %
<u>13-35-14-2</u>	<u>8-3-59</u>	<u>Utirik</u>
NEGATIVE NO.	DATE	SITE
BARRACKS BLDG. / 2		



CLASSIFICATION	OUO	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	CCB	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS _____ %
13-35-14-3	8-3-59	Utirik
NEGATIVE NO.	DATE	SITE
Dayroom BLDG # 3		



CLASSIFICATION	OUO	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	CCB	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS _____ %
13-35-14-4	8-3-59	Utirik
NEGATIVE NO.	DATE	SITE
OPERATIONS & SUPPLY BLDG. # 5		



CLASSIFICATION	OUO	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	COE	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS..... %
13-35-11-5		
NEGATIVE NO.	DATE	SITE
PUMP SHED BLDG. # 4		




CLASSIFICATION	OUO	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	COE	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS..... %
13-35-11-6	8-3-59	Utirik
NEGATIVE NO.	DATE	SITE
PUMP SHED BLDG. # 6		



CLASSIFICATION	OOO	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	COB	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS.....%
<u>13-35-14-7</u>	<u>8-3-59</u>	<u>Utirik</u>
NEGATIVE NO.	DATE	SITE
KEEPER BANK BLDG # 7		




CLASSIFICATION	OOO	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	COB	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS.....%
<u>13-35-14-8</u>	<u>8-3-59</u>	<u>Utirik</u>
NEGATIVE NO.	DATE	SITE
KEEPER BANK BLDG # 8		




CLASSIFICATION	000	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	CCS	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS _____ %
<u>13-35-14-9</u>	<u>8-3-59</u>	<u>Utirik</u>
NEGATIVE NO.	DATE	SITE
WATER TOWER BLDG. #9		



CLASSIFICATION	000	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	CCS	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS _____ %
<u>13-35-14-10</u>	<u>8-3-59</u>	<u>Utirik</u>
NEGATIVE NO.	DATE	SITE
POWER & DISTILLATION BLDG. # 10		



CLASSIFICATION	CUO	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	COE	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS _____ %
<u>13-35-16-11</u>	<u>8-3-59</u>	<u>Utirik</u>
NEGATIVE NO.	DATE	SITE
P12R		



A D D E N D U M * * N O . 6

RAD-SAFE STATION — WOTHO

PHOTOS

3 AUGUST 1959





CLASSIFICATION OUO INFORMATION
 PHOTOGRAPHER COE PICTORIAL
 PROGRESS _____ %
13-35-14-12 8-3-59 Wotbo
 NEGATIVE NO. DATE SITE
REFSER, DAYROOM, AND MESSHALL TENTS



CLASSIFICATION OUO INFORMATION
 PHOTOGRAPHER COE PICTORIAL
 PROGRESS _____ %
13-35-14-13 8-3-59 Wotbo
 NEGATIVE NO. DATE SITE
MESSHALL TENTS / 1 & 2



CLASSIFICATION	CUO	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	COE	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS _____ %
13-35-14-14	8-3-59	Yoko
NEGATIVE NO.	DATE	SITE
QUARTERS TENT # 3 AND BASSAFE TENT		


13-35-14-14



CLASSIFICATION	CUO	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	COE	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS _____ %
13-35-15-15	8-3-59	Yoko
NEGATIVE NO.	DATE	SITE
POWER & DISTILLATION BLDG.		



CLASSIFICATION	OCB	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	COE	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS _____ %
13-35-14-16	8-3-59	Mothe
NEGATIVE NO.	DATE	SITE
PIT LATRINE		



CLASSIFICATION	OCB	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	COE	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS _____ %
13-35-14-17	8-3-59	Mothe
NEGATIVE NO.	DATE	SITE
FIELD SHOWER		



CLASSIFICATION	000	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	CCB	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS
13-33-14-18	8-7-57	Water
NEGATIVE NO.	DATE	SITE
PUMP HOUSE		



CLASSIFICATION	000	<input checked="" type="checkbox"/> INFORMATION
PHOTOGRAPHER	CCB	<input type="checkbox"/> PICTORIAL
		<input type="checkbox"/> PROGRESS
13-35-14-19	8-3-57	Water
NEGATIVE NO.	DATE	SITE
WATER TOWER		