Reproduced from the holdings of the National Archives

Pacific Southwest Region

HOLMES & NARVER, Inc.

JOB:_

RE:__

DAVE	NARVER,	JR.	V
DHAD	TIMELVIIII .	OIL	•

FROM:

ENGINEERS-CONSTRUCTORS

0/S 6546 884

Hen Elen

R. A. BOETTCHER

ELECTRICAL SERVICE FOR BLDG. #413

1 AUGUST 1953

Ref .: 1. 3230-EE-6, Pwr. Dist., Area 10

2. 3285-EE-3, Elec Plan, Bldg. #413

The electrical service for Building #413 is being installed to pole F9 as shown on Reference 2.

Reference 1 shows the electrical service for Building #413 from pole F8 with a span of 3 # 8 between pole F8 and F9. This should be removed from the drawing.

Please add a detail to Reference 2 showing the installation of multibreaker panel and main switch. If the service equipment is not dustand water-tight it is suggested that the equipment be enclosed in a wood cabinet with a heater or a 100 watt lamp to lower the humidity.

RAB: JLM: jws

RESIDENT ENGINEER

cc: HO Chrono

HO Central

OS Chrono

OS Central

OS Engineering (Elec.)

1. Butther.

NATIONAL ARCHIVES REPOSITORY PACIFIC SOUTHWEST REGION

COLLECTION RG 326 ATOMIC ENERGY COMMISSION

BOX No. 199624 (#608) A16334 326-65V0170

ELMER GENERAL

FOLDER JUB 884 PROJECT ENGINEERING FILE

BEST COPY AVAILABLE