Reproduced from the holdings of the National Archives

_JOB:884 0/S 6811 David L. Narver, Jr.

FROM: H. L. Dietze

RE Ambiguities on H. O. Site Plans

DATE: 22 September 1953

The following ambiguous conditions have been noted on Home Office Site Plans:

DWG. 2201-OB-1, Rev. 5

Site Peter.

- 1. Station 232.07 appears on the drawing in two places. Once at cood's: N 101,950; El23,179.46, and once at cood's: N 100,800; El21,800. Please clarify.
- 2. Revision Four calls for a change in the cood's of Stations 120.06-120.11, 130.01, 130.03, and 170.01. No change was made in the cood's of these stations on either revision Four or Five. Are these cood's correct?
- The distance to ground zero for station 102, Oboe should be 16,661.11 3. feet, according to HN 8710. Suggest correction to DWG.

DWG. 2250-J-17.

Site Janet.

Station 231.07 will not develop the given cood's using the given 4. azimuth and distance.

DWG. 2249-P-17 Rev. 2. Site Pearl.

5. Station 232.15 will not develop the given cood's using the given azimuth and distance. The azimuth appears to be an error.

DIG. 2227-D0-17 Rev. 1. Site Dog.

Note 2 states that stations 1403.07 - 1403.10 should have a clear line 6. of sight to stations 10 and 30. Are these stations to be oriented to a point half way between stations 10 and 30?

Request clarification as soon as conveniently possible.

DEPARTMENT OF ENERGY DECLASSIFICATION REVIEW CRIZED BY DETERMINATION [CIRCLE NUMBER(S)] T. CLASSIPICATION RETAINED & CLASSIFICATION CHANGED TO 5 CONTAINS NO DOE CLASSIFIED INTO COORDINATE WITH 6. CLASSIFICATION CANCELLED

HLD:JD:hu

cc: HO Chronological

HO Central Files

03 Chronological

05 Central Files

Of Engineering ourveyina (2)

H. L. Dietze

Resident Bhaineer.

"This macerial contains internation nate and the common of the Unity Court place. 300, 2003, 750 Property St. the same and a section and the section of the section and the

Coky & Cohen 1/24/53

1 3 4 4 4 4 1 84

COLLECTION RE SOX No