Reproduced from the holdings of the National Archives 405824 Pacific Southwest Region NATIONAL ARCHIVES

REPOSITORY PACIFIC SOUTHWEST REGION COLLECTION RG 326 ATOMIC ENERGY COMMISSION BOX No. 199624 (#608) A16334 326-65V0170 PRESIDENT ELMER GENERAL FOLDER JOB 884 PROJECT ENGINEERING EXEC VICE PRES V PRES & GEN MGR CH FISCAL OFFCR I ASST GEL MGE LX 48 \mathcal{I} OPER-1919 INDEE ACLATION PROBLEM SETT ESTE VIEW WUC81 OF HEL MAINNER HUE20 mo 65 1 4 3 1 44 OH DESIGN ENGR **HA024** CH PERHIC ENGR PROLEGER (X **HP67** SALES DIVISION RR UWLX ACC VIING SECRETALL DE UHPJA 12B ACTION TLA 254 R 210506Z AEC GRNC

BEST COPY AVAILABLE

FROM HOLMES AND NARVER ENIWETOK MI

TO HOLMES AND NARVER LOSA

RESTRICTED

CITE ENGMSG FIVE THREE ONE EIGHT

aurura 11/23 "This material contains information affecting the To Les within the most national defense of the Unit ing of the espionar days, id the U.S.C., Scco. 790 Saion in revelation of which in any

mapner to an up authorized necessing prohibited by law

DAVID NARVER JR FROM DIETZE RE DWG ONE TWO THREE EIGHT PD DWG SHOWS PARTITIONS BETWEEN ROOM ONE THREE AND ONE FIVE AND BETWEEN ONE FIVE

AND ONE FEVEN AS EXISTING PD THESE PARTITIONS DO NOT RPT NOT EXIST PD SHOULD THEY BE INSTALLED QUES PLEASE ADPISE

21/05072

5318